

Report ID: 19,279,391 Version: 1 23 Oct 2019 Created:

Make:	KIA	Model:	RIO	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	DLR632	Reg Expiry:	09 Aug 2020	Engine			L
WoF Expiry:	26 Feb 2020	Odometer:	187,689 Kms	Good No:	19279391	Oil level	~		
VIN:	KNADE243266105148	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	S P SC S D SC	-01-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			ZIS	HIL S	Operation	~		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HID				ᅰЦ	CV joints	~		
* = decals	SDSC 916			- Jul	S SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S S S D SC						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tvre	L
Minor stone chips in the windscreen ,minor surface rust inside rear tailgate roof edge and hinges ,								mm	
						Right front	e		mm
						Left rear			mm
Conditions During Pody Inspection, Wet						Right rear		-	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average						~		
Banolo	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
	_					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Wet						Central locking			
	uning resi		Wet			Remote locking	~		
Engine Ti	ming Mechanism:	Unknow	'n			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•		••						
Inspected by: Donovan Matara Date: 23 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....