

Basic Vehicle Condition Guide

Report ID: 19,280,198


Version: 1

Created: 01 Nov 2019

Make: Model: Ford Fiesta **Body Style:** Hatchback Year: 2007 Registration: **GQM218** Reg Expiry: 10 Jul 2020 WoF Expiry: **Odometer:** 09 Oct 2020 66,741 Kms **Good No:** 19280198 VIN: WF0HXXWPJH6B0016 Next Service: 68500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlights scratched,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	wear and tear,minor stains ,
Carpets	wear and tear,minor stains ,
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Donovan Matara 01 Nov 2019 Inspected by: Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
	•	
~		
~		
~		
	•	•
~		
~		
		~
~		
~		
•		
~		
~		
d depth	of tyre	es)
į	5	mm
3		mm
1	2	mm
2		mm
	Yes	
	Yes	
·	Yes	
V	Yes	
<i>V V</i>	Yes	
\(\times \)	Yes	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes	
<i>V V V</i>	Yes	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes	
<i>v</i>	Yes	
<i>v</i>	Yes	
<i>v</i>	Yes	
V V V V V V	Yes	
V V V V V V	Yes	
V V V V V V	Yes	
<i>v</i>	Yes	
V V V V V V	Yes	
V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
	v v v v v v ddepth	v v v v v v depth of tyre

Signature: