

Report ID: 19,280,271 Version: 1 10 Oct 2019 Created:

Make:	Volkswagen	Model:	Crafter	Body Style:	Van		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	HRH73	Reg Expiry:	28 Dec 2019	Engine	1		
WoF Expiry:	14 Dec 2019	Odometer:	135,140 Kms	Good No:	19280271	Oil level	~		
VIN:	WV1ZZZ2EZF6001426	Next Service:	flexible	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
					( D D C C	Performance	~		
Key:		-0	<u>s</u>		S D R SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	sw dla			715	HIL	Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					S SC	Clutch	~		
P = pin dent	110				세비	CV joints	~		
* = decals	ssc 916			-Jul-	BID SDC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S D R C						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	•	of tyre	L 25)
Minor stone chips in the windscreen ,spider rust on the roof ,								mm	
						Right front			mm
						Left rear	6		mm
Condition	ac During Rody Inc	aaction	\\/_+			Right rear	6		mm
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights			
						Tail lights	~		<u> </u>
Carpets	Good					Indicators	~		
Banala	LR inner de	oor trim missing	1			Dashboard warning lights	~		
Panels		_				Wipers (front & rear)	~		$\left  - \right $
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	Comments					Window winder RL	•		~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		<u> </u>
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	2 V		-
Road Con	ations During Test	Drive:	Wet			Remote locking	~		
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
	-1		- 1.1				•		
Inspected by: Donovan Matara Date: 10 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....