

Basic Vehicle Condition Guide

Report ID: 19,280,893


Version: 1

Created: 24 Sep 2019

Make: Model: Toyota Raum **Body Style:** Hatchback Year: 2005 Registration: HQS942 Reg Expiry: 07 Dec 2019 WoF Expiry: **Odometer:** 25 Oct 2019 182,172 Kms **Good No:** 19280893 VIN: 7AT0H638X14074755 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper needs alignment,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak, minor surface rust underneath body,

Interior Comments			
Seats	wear and tear,minor stains ,		
Carpets	passengers floor ripped, wear and tear ,		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

24 Sep 2019 Inspected by: Donovan Matara Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	1		-
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			1
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	· ·		mm
Right front	1.5		mm
Left rear	0		mm
Right rear		1	
Spare	Yes		mm
Suspension		103	
Suspension performance	V		
Steering performance	~		
Shock absorbers	V		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories	<u> </u>		
Head lights	~		
Tail lights			
Indicators	V		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	1		
Window winder FL	~		
Window winder FR	~		
Window winder RL			
Window winder RR	V		
Rear view mirrors			
	<i>V</i>		-
Radio (basic test only)	<i>V</i>		
CD (basic test only)	1		
Number of keys	1		
Central locking	-		-
Remote locking	-		<u> </u>
Sat. Nav. (basic test only)			'
Reversing camera	1	1	V

I have read and understood this condition guide.

Name:

Signature: