

Report ID: 19,281,386 Version: 1 01 Oct 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	EMD842	Reg Expiry:	01 Jul 2020	Engine	•		
WoF Expiry:	01 May 2020	Odometer:	206,225 Kms	Good No:	19281386	Oil level	~		
VIN:	WF0GXXGBBG7J06814	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged to	r an additional o	inarge.	Coolant condition	~		
	P SC S		P SC W P SC W	S	W	Performance	~		
ney:						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect C = crack S SC W S PT SC SC W						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent * = decels						CV joints	~		
e decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W S P SC W S P SC W S S S C W						Performance	~		
Body Incr	postion Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	V		
Body Inspection Comments Moisture in the headlights, crack in left front door frame, right rear reflector broken, scratch marks in						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
windscreen,									mm
						Right front		2	mm
						Left rear		2	mm
Conditions During Body Inspection: Wet						Right rear		2	mm
Conditions During Body Inspection. Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	stains thro	ughout, rip in dr	ivers seat ,			Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	stains thro	ughout, scuff ma	arks throughout ,			Dashboard warning lights	~		
	A					Wipers (front & rear)	-	~	
Dashboa	rd Average					Window winder FL	~	-	
						Window winder FR	~		
General Comments					Window winder RL	~			
No tools for spare wheel, one of the front wipers will need to be replaced,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Wet						Central locking	2 V		
						Remote locking	-	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
[									
Inspected by: Donovan Matara Date: 01 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....