

Report ID: 19,281,546 Version: 1 19 Sep 2019 Created:

Signature:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:	29 Jul 2020	Engine			<u> </u>
WoF Expiry:		Odometer:	191,001 Kms	Good No:	19281546	Oil level	~		
VIN:	KMFWBX7KLDU57556	Next Service:	195400	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	hoon discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
			SP*SC SD*			Performance	~		
Key:	S SC	-0	SP*SC SD*		S D C * SC	Radiator / Hoses (visual)	~		
S = scratch	TE			NOG	<u>کھر</u>	Transmission			1
D = dent R = rust	S D SC			715	SDC	Operation	~		
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~		
C = crack					S D SC	Clutch	~		
P = pin dent	HIP				74 <u>11</u>	CV joints	~		
* = decals	SPSC 916			The second	BID SD*	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant			S*SC SD*SC		S D *	Performance	~		
Body Incr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Panel under LR light broken ,						Tyres (lowest observed tread depth of tyres)			
Parlet under En light broken,						Left front	7	,	mm
						Right front	7	,	mm
						Left rear	3	8	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	wear and t	tear,minor stains	,			Head lights	~		
	rear hood	lining missing ,				Tail lights	~		
Carpets		J J,				Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR		_	~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	d by: Donovan Matar	a				Date: 19 Sep 20	19		

I have read and understood this condition guide.

Name: