

Report ID: 19,282,070 Version: 1 27 Sep 2019 Created:

Signature:

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
	2011		FZS779	Reg Expiry:	19 Apr 2020	Engine			
	02 Oct 2020	Odometer:	214,880 Kms	Good No:	19282070	Oil level	~		
	WF0GXXGBBGBE0640			Service History		Smoke & fumes	~		
			221000		110	Performance	~		
	oort is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		
Key:	SC	-0	S D SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	IS SC OF			The	EID S	Operation	~		
R = rust				10	JHIN	Noise	~		
PT = paint defe C = crack	ect			+	SC	Clutch	~		
P = pin dent	40					CV joints			~
* = decals	s sc pp			SI_	ELA SSC	,	~		
SC = stone chip	os Us	VA		10		Wheel bearings	~		
W = significant scuffs SC S S S S S S S S S S S S S S S S S S						Brakes			
		Notorcom				Performance	~		
Body Insp	ection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~	<u> </u>	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front		1	mm
						Right front		4	mm
						Left rear	4 mm		mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & Under BOI	met inspectic	on comments			Suspension	1	1	1
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Interior Comments						Electrical / Accessories		1	
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	omments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central							~		
			-			Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
·							10		
Inspected by: Donovan Matara Date: 27 Sep 2019									

I have read and understood this condition guide.

Name: