

Report ID: 19,296,257 Version: 1 03 Dec 2019 Created:

| Make: | Nissan | Model: | Wingroad | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|---------------------------------------|----------------------|--------------------------------------|----------|---------|----------|
| Year: | 2012 | Registration: | GLF3 | Reg Expiry: | 15 Jul 2020 | Engine | | | |
| WoF Expiry: | 17 Jul 2020 | Odometer: | 176,513 Kms | Good No: | 19296257 | Oil level | ~ | | |
| VIN: | JN1TBAY12A0040991 | Next Service: | 186000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for are and mileago | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust S SC | | | | | | Operation | ~ | | |
| PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | - | | ~ |
| P = pin dent | HID | | | | 74 <u>11</u> | CV joints | ~ | | • |
| * = decals | sc 916 | | | -No- | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| D lu lu | | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread | - | of tyre | es) |
| | | | | | Left front 4.0 mm | | | | |
| | | | | | | Right front | 4. | - | mm |
| | | | | | | Left rear | 3. | | mm |
| Condition | | a a ati a a . | D. | | | Right rear | | | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | stabiliser mount torn | • | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats drivers seat worn | | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Demolo | Average | | | | | Dashboard warning lights | ~ | | |
| Panels | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Average | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FE | ~ | | |
| General C | Comments | | | | | Window winder RL | ~ | | |
| Battery failed load test | | | | | | Window winder RL Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | | | |
| Road Conditions During Test Drive: Dry | | | | | | - | 1 | | |
| Koad Con | ditions During Test | t Drive: | Dry | | | Central locking | v | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Remote locking | ~ | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | v |
| | | | | | | Reversing camera | | | ~ |
| Inspected by: Greg Morgan Date: 02 Dec 2019 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: