

Basic Vehicle Condition Guide

Report ID: 19,359,969


Version: 3

Created: 08 Mar 2022

Make: Model: Suzuki Vitara **Body Style:** SUV Year: 2019 Registration: MBB217 Reg Expiry: 17 Mar 2022 WoF Expiry: **Odometer:** 18 Nov 2022 46,526 Kms **Good No:** 19359969 VIN: TSMLYDA1S00625793 Next Service: 51600 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor crack CVA, both mirror casings scratches, both sill mouldings scratches, Minor stone chips on windscreen.

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Drives well,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Date: 09 Nov 2021 Inspected by: Donovan Matara

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	4	.0	mm
Left rear	2	.5	mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	>		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	ı	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		

I have read and understood this condition guide.

Name:

Signature: