

Report ID: 19,362,691 Version: 4 11 Jun 2020 Created:

Make:	Toyota	Model:	Spacio	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	1997	Registration:	DSZ839	Reg Expiry:	01 Oct 2020	Engine				
WoF Expiry:	15 May 2020	Odometer:	185,006 Kms	Good No:	19362691	Oil level	~			
VIN:	7A8H6350707043106	Next Service:	195016	Service Histor	y: No	Smoke & fumes	r			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	r			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	s	-0	LS	$-\square$	s	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust	PTW 6/6			ZIN		Operation	~			
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~			
C = crack					РТ	Clutch			~	
P = pin dent	110				세비	CV joints		~		
* = decals	P 916			-Jul-	ELD SC	Wheel bearings	~	-		
SC = stone chips						Brakes				
W = significant scuffs C W S D D SC W						Performance	~			
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread	•	oftvre	es)	
Stone chips front screen. Tailgate badge missing. Left mirror wont retract or adjust								mm		
						Right front		4.0 mm		
						Left rear			mm	
Conditions During Pody Inspection, Wet						Right rear	4.0 mm 3.0 mm			
Conditions During Body Inspection: Wet						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	blit and joints are noisy	·				Suspension performance	~			
	, ,					Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Jeats						Tail lights	~			
Carpets	Average						~			
Damala	Good					Dashboard warning lights	~			
Panels						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FE	<i>v</i> <i>v</i>			
General Comments					Window winder RL	<i>v</i> <i>v</i>				
						Window winder RE	<i>v</i> <i>v</i>			
						Rear view mirrors	-	~		
						Radio (basic test only)	~	-		
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Wet						Central locking	· ·			
Koad Con	attions During Test	u Drive:	Wet			Remote locking	-		~	
Engine Tir	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			<i>v</i> <i>v</i>	
Evidence of Cam Belt Replacement: Yes Kms: 150,000						Reversing camera			v v	
	-1								•	
Inspected by: Brian Hill Date: 04 Jun 2020										

I have read and understood this condition guide.

Name:

Signature: