

Basic Vehicle Condition Guide

Report ID: 19,375,708


Version: 6

Created: 21 Jul 2020

Make: Model: Holden Colorado **Body Style:** Utility Year: 2016 Registration: JZP17 Reg Expiry: 05 Aug 2020 WoF Expiry: **Odometer:** 20 May 2021 78,766 Kms **Good No:** 19375708 VIN: MMU148PK0GH64475 **Next Service:** 84000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front and rear bumpers misaligned Rear cargo body cover damaged Stone chip crack on front windscreen Mirror switch insecure

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Good | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

1 key cover broken

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 21 Jul 2020

Name:

| | Pass | Fail | N/A | |
|--|---------------------------------------|------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | \(\triangle \) | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 3 | mm | |
| Right front | | 3 | mm | |
| Left rear | | 3 | mm | |
| Right rear | | 5 | mm | |
| Spare Yes | | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\triangle \) | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | | | |
| Central locking | • | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ' | |
| Reversing camera | ~ | | | |

Signature: