



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,427,514
Version:	2
Created:	04 Feb 2020

Make:	Mazda	Body Style:	Hatchback
Model:	Demio	VIN:	7AT0C12HX19117465
Year:	2009	Odometer:	92,102 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>							
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•					
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good					
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good					
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good					
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		7	mm					
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	7	mm		87	L/F Guard	Good				
9	Reversing Lights	✓	38	Wheel Bearing	✓	63	Left Rear	7	mm		88	R/F Guard	Good				
10	Rear Reflectors	✓	39	Wheel Balance	✓	64	Right Rear	7	mm	89	L/H Doors	Good					
11	Hazard Lights	✓	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	90	R/H Doors	Good			
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	68	Heater Fan	✓	91	L/H Sill	Good			
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable		69	Seatbelts	✓	70	Horn	✓	92	R/H Sill	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓	93	Boot/Tail Gate	Good			
15	Number Plate Light	✓	Brakes		Interior		73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	94	Front Bumper	Good		
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	75	Carpets	Good	76	Panels	Good	95	Rear Bumper	Good			
17	Speedo	✓	45	Rear Brakes	✓	77	Dashboard	Good	96	Roof	Good	97	Bonnet	Good			
18	Odometer	✓	46	Handbrake	✓				98	Fuel Cap	✓	99	Mud Flaps	✓			
19	Rev Counter	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	2	100	WOF	✓	
20	Fuel Gauge	✓	48	Remote Locking	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓				
21	Wipers Front/Rear	✓	49	Number of Keys	2	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓			
22	Window Opener FL	✓	Engine		55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓				
23	Window Opener FR	✓	50	Oil Level	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓			
24	Window Opener RL	✓	51	Smokes and Fumes	✓	61	Left Front	7	mm	62	Right Front	7	mm				
25	Window Opener RR	✓	52	Performance	✓	63	Left Rear	7	mm	64	Right Rear	7	mm				
26	Rear View Mirrors	✓	53	Noise	✓	65	Spare	N/A	66	Tools	✓						
27	Radio (Basic Test Only)	✓	54	Starter Motor	✓	67	AC Operation	✓	68	Heater Fan	✓						
28	CD (Basic Test Only)	✓				69	Seatbelts	✓	70	Horn	✓						
29	Boot Open Switch	✓				71	Seat Heaters	•	72	Sun Visors	✓						

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	04 Feb 2020
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--