



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,431,092
Version:	1
Created:	29 Nov 2019

Make:	Honda	Body Style:	Hatchback
Model:	FIT	VIN:	7AT08G2YX19416993
Year:	2010	Odometer:	94,478 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>					
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•			
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good		
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		7	mm			
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	7	mm		87	L/F Guard	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	63	Left Rear	7	mm		88	R/F Guard	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓	64	Right Rear	7	mm	89	L/H Doors	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	•	65	Spare	No	66	Tools	✓	90	R/H Doors	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	91	L/H Sill	Good	92	R/H Sill	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable		68	Heater Fan	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		69	Seatbelts	✓	95	Rear Bumper	Good	96	Roof	Good	
15	Number Plate Light	✓	Brakes		Interior		70	Horn	✓	97	Bonnet	Good	98	Fuel Cap	✓
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	71	Seat Heaters	•	72	Sun Visors	✓	99	Mud Flaps	✓	
17	Speedo	✓	45	Rear Brakes	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	100	WOF	✓	
18	Odometer	✓	46	Handbrake	✓	75	Carpets	Good	76	Panels	Good				
19	Rev Counter	✓	Keys and Locking		77	Dashboard	Good								
20	Fuel Gauge	✓	47	Central Locking	✓										
21	Wipers Front/Rear	✓	48	Remote Locking	✓										
22	Window Opener FL	✓	49	Number of Keys	1										
23	Window Opener FR	✓	Engine												
24	Window Opener RL	✓	50	Oil Level	✓										
25	Window Opener RR	✓	51	Smokes and Fumes	✓										
26	Rear View Mirrors	✓	52	Performance	✓										
27	Radio (Basic Test Only)	✓	53	Noise	✓										
28	CD (Basic Test Only)	✓	54	Starter Motor	✓										
29	Boot Open Switch	✓													

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	29 Nov 2019
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--