

Report ID: 19,431,777 Version: 1 27 Nov 2019 Created:

Make:	Isuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	JUU238	Reg Expiry:	29 Jun 2020	Engine			1
WoF Expiry:	04 Jul 2020	Odometer:	55,948 Kms	Good No:	19431777	Oil level	~		
VIN:	MPATFR85JGT000933	Next Service:	60000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
			S		S D	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			I
R = rust	s sc			210		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	sc				2416	CV joints			~
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
- Significan	S		D			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3.5 mi		mm
						Right front	4.5 m		mm
						Left rear	3.	5	mm
Conditions During Body Inspection:						Right rear	4 mr		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua	iu l					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		1
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicmy Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Stuart Melbourne Date: 27 Nov 2019									

Name: