

Basic Vehicle Condition Guide

Report ID: 19,468,330

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance

Steering performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Shock absorbers

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 23 Apr 2019

Pass

1

~

/

V

1

3.5

3.5

5.5

1

/

/

1

/

V

1

1

Yes

Tyres (lowest observed tread depth of tyres)

Fail

N/A

1

mm

mm


mm

 mm

Make: Hyundai Model: Sonata **Body Style:** Sedan Year: 2008 Registration: FWH142 **Reg Expiry:** 01 Aug 2019 WoF Expiry: **Odometer:** 22 Jun 2019 303,867 Kms **Good No:** 19468330 VIN: KMHEU41VR8A45803: Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RL window switch and FL window not functioning FR door handle insecure

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

underbody surface rust Left sill dent and crack Engine oil leak FR outer cv boot leak

Interior	Comments

Seats	rear seat torn
Carpets	Average
Panels	Average
Dashboard	crack on the dashboard

General Comments

Inspected by:

Rear brake noisy and brake pads need to change

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

I have read and understood this condition guide.

Sudhin Ramachandran

	Sat. Nav.	Sat. Nav. (basic test only)		·	
Kms:	Reversin	Reversing camera		V	
Date: 23 Apr 2019					
Name:		Signature:			