

Report ID: 19,468,463 Version: 2 07 May 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV][Pass	Fail	N/A	
Year:	2006	Registration:	JJA130	Reg Expiry:	15 Nov 2018		Engine				
WoF Expiry:	07 Apr 2019	Odometer:	177,341 Kms	Good No:	19468463		Oil level	~			
VIN:	6FPAAAJGAT5K28892	Next Service:	0	Service Histor	y: No		Smoke & fumes	~			
						it	Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	١ŀ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Iŀ	Coolant condition	~			
	S D SC		S D SC S D SC		S P SC	۱Ē	Performance	~			
Key:	13030	$-\infty$	3030 3030		3F3C		Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission				
D = dent R = rust	S D C SC			715	SDC	۱ŀ	Operation	~			
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$			Noise	~			
C = crack					S SC	lŀ	Clutch			~	
P = pin dent	HIP				74116	lŀ	CV joints	~			
* = decals SC 99 SDC						۱ŀ	Wheel bearings	~			
SC = stone chips W = significant scuffs							Brakes				
W = significant scutts S P SC S D SC S P SC S P SC							Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	۱ŀ	Hand Brake	~			
Body Inspection Comments Spare wheel is on LR,							Fyres (lowest observed tread	depth	of tyre	es)	
Spare wheel is on Eng										mm	
						lŀ	Right front		3	mm	
						J╞	Left rear			mm	
Conditions During Body Inspection: Dry						۱ŀ	Right rear	5 mm		mm	
						ļŀ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
							Suspension performance	~			
						١ŀ	Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater	1		1	
L						łŀ	Operation	~			
Interior Comments						[Electrical / Accessories				
Seats	wear and t	ear,minor stains	,				Head lights	~			
	wear and t	ear,minor stains					Tail lights	~			
Carpets		,	,				Indicators	~			
Panels	Average						Dashboard warning lights		~		
	Average						Wipers (front & rear)	~			
Dashboa	rd						Window winder FL	~			
						¦ſ	Window winder FR	~			
General Comments					[Window winder RL	~				
Check engi	ne light is on ,					[Window winder RR	~			
						ļſ	Rear view mirrors	~			
						[Radio (basic test only)	~			
						[CD (basic test only)	~			
						۱Ľ	Number of keys 1				
Road Conditions During Test Drive: Dry][Central locking	~			
			•			ŗſ	Remote locking	~			
Engine Timing Mechanism: Unknown						[Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:			Reversing camera	~			
la a	Inspected by: Donovan Matara Date: 07 May 2010										
Inspected by: Donovan Matara Date: 07 May 2019											

I have read and understood this condition guide.

Name:

Signature: