

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or		Noise	~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Cooling System		
a fuil mechanical inspect	ion phor to purchase and this can be arranged for an additional charge.	Coolant condition	~	
		Performance	~	
Key:		Radiator / Hoses (visual)	~	
S = scratch D = dent R = rust S SC W		Transmission		
		Operation	~	
PT = paint defect		Noise	~	
		Clutch		~
P = pin dent		CV joints	~	
* = decals PT SC		Wheel bearings	<b>v</b>	
SC = stone chips		Brakes	•	
W = significant scuffs		Performance	~	
	Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
Body Inspection Comments			-	f tyres)
		Tyres (lowest observed tread depth of tyres)   Left front 4.0 mm		
		Right front		
			4.0	mm
		Left rear	4.0	mm
Conditions During Body Inspection: Dry		Right rear	6.0	mm
Under Carriage & Under Bonnet Inspection Comments		Spare Yes		
onder Carriage & onder bonnet inspection Comments		Suspension		
		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater		
Interior Comments		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Average	Head lights	~	
Carpata	Average	Tail lights	~	
Carpets		Indicators	~	
Panels	roof lining loose	Dashboard warning lights	~	
	Average	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
		Window winder FR	~	
General Comments		Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)	~	
		Number of keys	1	I
Road Conditions During Test Drive: Dry		Central locking	~	
		Remote locking	~	
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)	-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera		~
				•
Inspected by: Greg Morgan Date: 30 Apr 2019				

I have read and understood this condition guide.

Name: .....

Report ID: 19,468,714

Pass

V

V

V

1

16 May 2019

Fail

N/A

Version:

Created: