

Report ID: 19,468,896 Version: 4 28 Jun 2019 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Sedan	1		Pass	Fail	N/A	
Year:	2007	Registration:JQC739Reg Expiry:29 Jan 2020				En	Engine				
WoF Expiry:	05 Jul 2020	Odometer:	82,226 Kms	Good No:	19468896		)il level	~			
VIN:	7AT0GF0BX15018061	Next Service:		Service Histor	<b>y:</b> No	S	moke & fumes	~			
						i P	erformance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							loise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							coolant condition	~			
						1   P	erformance	~			
Key:	S	-0	S S	-	s		adiator / Hoses (visual)	~			
S = scratch						Tra	ansmission				
D = dent R = rust SC SPT SC							Operation	~			
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$			loise	~			
C = crack							lutch	•		~	
P = pin dent					세비		V joints	~			
* = decals				- No	ELD's		Vheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs W S S W S							erformance	~			
Note: come defects & blamiches may not be displayed in the disprem							land Brake	~			
Body Inspection Comments								•	oftyre	) )	
						Tyres (lowest observed tread depth of tyres)           Left front         7.5 mm					
							light front		-	mm	
							eft rear	4.			
						<b>- ا</b> -		6		mm	
Conditions During Body Inspection: Wet							Right rear 6 mm				
Under Carriage & Under Bonnet Inspection Comments							Spare Yes Suspension				
AWD	indge a onder boi	meemspeede	<u>Comments</u>				•				
AWD							uspension performance	~			
							teering performance	~			
							hock absorbers	~			
							Air Conditioning / Heater				
Interior Comments							Operation 🖌				
Good							Electrical / Accessories				
Seats	Good						lead lights	~			
Carpets	Good					T	ail lights	~			
	Card					h	ndicators	~			
Panels	Good						ashboard warning lights	~			
Dashboa	crack on d	lash board					Vipers (front & rear)	~			
							Vindow winder FL	~			
	<b>-</b> .					īĽ	Vindow winder FR	~			
<u>General Comments</u>						V	Vindow winder RL	~			
						V	Vindow winder RR	~			
						R	lear view mirrors	۲			
						R	adio (basic test only)	~			
							D (basic test only)	~			
						┘┌╷	Number of keys 2				
Road Conditions During Test Drive: Dry							entral locking	~			
			•				emote locking	~			
Engine Timing Mechanism: Timing Chain						s	at. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						R	eversing camera			~	
Inspected by: Sudhin Ramachandran Date: 28 Jun 2019											

Name: .....