

Basic Vehicle Condition Guide

Report ID: 19,468,910


Version: 3

Created: 27 May 2019

Make: Model: MPV Mazda **Body Style:** SUV Year: 2011 Registration: HYL658 Reg Expiry: 03 Nov 2019 WoF Expiry: **Odometer:** 25 May 2020 138,866 Kms **Good No:** 19468910 VIN: 7AT0C11EX15226393 **Next Service:** 146261 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

FL side mirror auto folding not working

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2WD

| | Interior Comments | | | | |
|--|-------------------|---------|--|--|--|
| | Seats | Average | | | |
| | Carpets | Average | | | |
| | Panels | Average | | | |
| | Dashboard | Average | | | |

| _ | _ |
|---------|----------|
| Conoral | Comments |
| General | COMMENTS |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Sudhin Ramachandran Inspected by:

| Created: 27 May 2019 | | | | | | | |
|--|----------------------------|------|-----|--|--|--|--|
| | Pass | Fail | N/A | | | | |
| Engine | | | | | | | |
| Oil level | ~ | | | | | | |
| Smoke & fumes | ~ | | | | | | |
| Performance | ~ | | | | | | |
| Noise | ~ | | | | | | |
| Cooling System | | | | | | | |
| Coolant condition | ~ | | | | | | |
| Performance | ~ | | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | | |
| Transmission | | | | | | | |
| Operation | | | ~ | | | | |
| Noise | | | ~ | | | | |
| Clutch | | | ~ | | | | |
| CV joints | ~ | | | | | | |
| Wheel bearings | ~ | | | | | | |
| Brakes | | | | | | | |
| Performance | ~ | | | | | | |
| Hand Brake | ~ | | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | | |
| Left front | 3.0 | | mm | | | | |
| Right front | 3.0 | | mm | | | | |
| Left rear | 6.5 | | mm | | | | |
| Right rear | 6.0 | | mm | | | | |
| Spare N | | N/A | | | | | |
| Suspension | | | | | | | |
| Suspension performance | ~ | | | | | | |
| Steering performance | ~ | | | | | | |
| Shock absorbers | ~ | | | | | | |
| Air Conditioning / Heater | | | | | | | |
| Operation 🗸 | | | | | | | |
| Electrical / Accessories | | I | | | | | |
| Head lights | ~ | | | | | | |
| Tail lights | ~ | | | | | | |
| Indicators | ~ | | | | | | |
| Dashboard warning lights | V V V V V V | | | | | | |
| Wipers (front & rear) | ~ | | | | | | |
| Window winder FL | ~ | | | | | | |
| Window winder FR | ~ | | | | | | |
| Window winder RL | ~ | | | | | | |
| Window winder RR | ~ | | | | | | |
| Rear view mirrors | ~ | | | | | | |
| Radio (basic test only) | ~ | | | | | | |
| CD (basic test only) | ~ | | | | | | |
| Number of keys | 1 | • | • | | | | |
| Central locking | ~ | | | | | | |
| Remote locking | ~ | | | | | | |
| Sat. Nav. (basic test only) | | | ~ | | | | |
| Reversing camera | | | ~ | | | | |
| | | | | | | | |

I have read and understood this condition guide.

Name:

Signature:

17 May 2019

Date: