

Basic Vehicle Condition Guide

Report ID: 19,469,196


Version: 2

Created: 13 May 2019

Make: Model: Suzuki Wagon R+ **Body Style:** Wagon Year: 1999 Registration: YS8962 Reg Expiry: 28 May 2019 **Odometer: Good No:** WoF Expiry: 12 Nov 2019 132,483 Kms 19469196 VIN: JSAEMA81S00303113 Next Service: 142500 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Left front door mould broken. Right taillight cracked. Minor stone chips front screen.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Slight oil leak

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Pass	Fail	N/A
~		
>		
'		
>		
/		
~		
~		
~		
~		
/		
'		
>		
>		
>		
l depth	of tyre	:s)
2	.0	mm
2	.0	mm
3.0		mm
3.0		mm
	Yes	
/		
>		
~		
		~
		'
V		<i>'</i>
<i>y</i>		<i>V</i>
<i>y y y</i>		<i>'</i>
<i>y y y y</i>		V
V V V		<i>V</i>
V V V V		
V V V V		
V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V		
V V V V V V V		
>		
V		
V		
	ママママママママママママママママママママママママママママママママママママ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature:

30 Apr 2019

Reversing camera