

Report ID: 19,469,545 Version: 1 29 Apr 2019 Created:

Make:	Ford	Model:	Falcon	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	DKH281	Reg Expiry:	02 Apr 2019	Engine	1	I	1
WoF Expiry:	03 Oct 2019	Odometer:	192,341 Kms	Good No:	19469545	Oil level	~		
VIN:	6FPAAAJGSW6J89296	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC W		S SC S		S SC	Performance	~		
Key:		-0		500-	330	Radiator / Hoses (visual)	~		
S = scratch	TE				Tan	Transmission	1		
D = dent R = rust	s sc			710	HIVS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc				74114	CV joints	~		
* = decals		10		10	S SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincari	SC W		P SC S D		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Petrol flap rusty. Rust in seam LH side of boot lid on body. Surface rust on inside of boot floor.						Tyres (lowest observed tread depth of tyres)			es)
Roof lining coming off. RF seatbelt not retracting properly. Wear on steering wheel, console and door cards. Hands free fitted. RR window not working well. LR door inner trim damaged.						Left front	5 mm		
Hands free	fitted. RR window not w	vorking well. LR c	loor inner trim damag	ed.		Right front	:	3	mm
						Left rear		2	mm
Conditions During Body Inspection: Wet						Right rear	3 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	t on seams on RF inner g					Suspension performance	~		
front suspe	nsion over bumps. Surfa	ace rust under fic	oor. Rear suspension c	rossmember is r	usty.	Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation			~
Interior Comments						Electrical / Accessories	-		
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concret						Window winder FR	~		
General Comments						Window winder RL	~		
Gas struts on boot lid not working. Stonechips on windscreen. RF seat has wear. Remote locking not working. Surface rust marks on inner seams of RF,LF and RR doors. RH						Window winder RR	~		
sill has rust.						Rear view mirrors	~		
Drives ok.						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timing (				Remote locking		~	
-	of Cam Belt Replac	•		Kms:		Sat. Nav. (basic test only)			~
Lvidence	or carri bert nepiac		lot Applicable	11113.		Reversing camera			~
Inspected	d by: Roger King					Date: 29 Apr 20	19		
· ·	· - •					· .			

I have read and understood this condition guide.

Name: .....

Signature: .....