

Basic Vehicle Condition Guide

Report ID: 56,592

Version: 2

Created: 21 May 2019

Pass


Fail

N/A

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: 2006 Registration: DJY10 Reg Expiry: 17 Feb 2020 **WoF Expiry: Odometer:** 13 May 2020 161,207 Kms **Good No:** 19470514 VIN: WVWZZZ1KZ6U01446 Next Service: Freshly Serviced Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

J Ottesen

Evidence of Cam Belt Replacement: Yes

Kms: 120,000

| Engine | | | |
|------------------------------|--|---------|-----|
| Oil level | ~ | | |
| Smoke & fumes | V V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | \(\triangle \) | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | \(\times \) \(\t | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | depth | of tyre | es) |
| Left front | : | 2 | mm |
| Right front | 3 | .0 | mm |
| Left rear | 6 | .0 | mm |
| Right rear | 6 | 6.0 mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | \(\triangle \) | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | 1 |

I have read and understood this condition guide.

Name:

Signature:

30 Apr 2019