

Basic Vehicle Condition Guide

Report ID: 19,470,885

Pass

~

~

/

1

5.5

5.5

4.5

4.5

1

/

/

/

1

1

2

Yes

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance

Steering performance

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Shock absorbers Air Conditioning / Heater

Spare

Coolant condition

Created: 28 Apr 2019

Fail

N/A

1

mm

mm


mm

 mm

Make: Model: Hyundai Elantra **Body Style:** Sedan Year: 2007 Registration: EEN174 **Reg Expiry:** 28 Oct 2019 WoF Expiry: **Odometer:** 18 Oct 2019 120,993 Kms **Good No:** 19470885 VIN: KMHDT41DR7U25212 Next Service: 132000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Rattling noise from rear

Inspected by:

Road Conditions During Test Drive: Wet

Sudhin Ramachandran

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: 103,661 Yes

Remote locking Sat. Nav. (basic test only) 1 Reversing camera 1 Date: 28 Apr 2019

have read and understood this condition quide.	Name:	Signature: