

Road Conditions During Test Drive: Wet
Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: Yes

214,000

Kms:

Name: .....

29 Apr 2019

V

V

V

I have read and understood this condition guide.

**Dion Mair** 

Inspected by:

Signature: .....

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date: