

Report ID: 19,471,917 Version: 3 06 Jun 2019 Created:

Make:	Honda	Model:	Elysion	Body Style:	SUV		Pass	Fail	N/A
Year:	2006		LDP120	Reg Expiry:	08 May 2019	Engine			
WoF Expiry:		Odometer:	112,860 Kms	Good No:	19471917	Oil level	~		
VIN:	7AT08GBPX17108943		,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	v v		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance			
Key:	SC	-0	DW W		P W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent							Operation 🖌		
R = rust				10		· · ·	-		
PT = paint defe	ect			$\square \cup$		Noise	~		
C = crack P = pin dent	Ho			-		Clutch			~
* = decals	SDPSC DC					CV joints	~		
SC = stone chips						Wheel bearings	bearings 🖌		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Windscreen stone chips/Rear wiper worn/Reverse camera blurry/Right taillight fail/Right sliding door fail to						Tyres (lowest observed tread depth of tyres)			
hold still						Left front	2	.5	mm
						Right front	3	3	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Wet					Right rear	7 mm		mm	
					Spare	are Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Front wheel drive Aftermarket lowering springs						Suspension performance	~		
Antermarke	riowening springs					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		-	
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights		~	
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
	. Poor					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Ca Thach Date: 06 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: