

Report ID: 19,473,065 Version: 1 30 Apr 2019 Created:

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A	
Year:	2005	Registration:	CZL918	Reg Expiry:	31 Oct 2019	Engine			L	
WoF Expiry:	09 Jul 2019	Odometer:	288,525 Kms	Good No:	19473065	Oil level	~			
VIN:	JF2BPEKUA6G035268	Next Service:	0	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for and mileage	Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:	S SC	$\neg$	S P SC S P SC		S SC	Radiator / Hoses (visual)	~			
S = scratch	STE	A U			X.	Transmission	•		L	
D = dent	s sc dl				SDC	Operation	~			
R = rust PT = paint def				$\prod$	THA	Noise	~			
C = crack				+	SC	Clutch			~	
P = pin dent						CV joints		~		
* = decals	SDSC 916			T	ELIPE S	Wheel bearings		~		
SC = stone chips						Brakes		v		
W = significan	t scuffs S SC	-	S SC S SC		Is	Performance	~		<u> </u>	
		Note: son	he defects & blemishe	s may not be disn	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre		
Minor stone chips in the windscreen,front bumper needs alignment ,						Left front 3 mm				
						Right front		5 7	mm	
						Left rear				
							3 mm			
Conditions During Body Inspection: Dry						Right rear 6 mm			mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Minor oil leak, CVS need checking as well as the bushes on the front steering rack and suspension rear,						Suspension				
Millior on le	ak, CV3 need checking a	is well as the bus	nes on the nont steen	ing fack and susp		Suspension performance		~		
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation		~		
		tear,minor stains				Electrical / Accessories			<u> </u>	
Seats						Head lights	~			
Carpets	Average					Tail lights	~			
	wear and t	tear,worn,minor	stains			Indicators	~			
Panels						Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~			
General	<u>Comments</u>					Window winder FR	~		<u> </u>	
						Window winder RL	~		──	
						Window winder RR	~		<u> </u>	
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	~			
L						Number of keys	2			
Road Conditions During Test Drive: Dry							~		<u> </u>	
Enging Ti	ming Machanism	Timina	Chain			Remote locking	~		<u> </u>	
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspecte	Inspected by: Donovan Matara Date: 30 Apr 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....