

Report ID: 19,473,286 Version: 1 01 May 2019 Created:

Make:	Toyota	Model:	Allion	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2004	Registration:	JEN524	Reg Expiry:	23 Jun 2019	Engine	1		I	
WoF Expiry:		Odometer:	158,057 Kms	Good No:	19473286	Oil level	~			
VIN:	7AT0H645X15026347	Next Service:	162463	Service Histor	y: No	Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		C 1 1	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	s w	-0	S SW		S	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent SC D D S						Operation	~			
R = rust				10	JHIN	Noise	~			
PT = paint defe C = crack				$\square \cup$		Clutch	V		~	
P = pin dent	40				JUII ——	CV joints	~		V	
* = decals	- MIK			AL-	ENPRIS T	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S W S S S S S S										
						Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	hayed in the diagram	Hand Brake		<u>.</u>	Ļ	
FL bumper parking sensor missing						Tyres (lowest observed tread depth of tyres)				
						Left front	-	3	mm	
						Right front	4.		mm	
						Left rear		3 mm		
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
2WD Engine and transmission oil leak						Suspension performance	~			
Leak on FR inner cv boot						Steering performance	~			
Rear trail arm bush crack from both sides						Shock absorbers	~			
						Air Conditioning / Heater				
Interior C						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	۲			
						Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	<			
Rear brake i	noisy					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry Central locking										
			•			Remote locking			~	
-	ning Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Sudhin Ramachandran Date: 01 May 2019										

I have read and understood this condition guide.

Name:

Signature: