

Report ID: 19,473,319 Version: 1 01 May 2019 Created:

Make:	Nissan	Model:	March	Body Style:	Hatchback	] [	Pass	Fail	N/A
Year:	2002	Registration:		Reg Expiry:	18 Jun 2019	Engine			
WoF Expiry:	05 Oct 2019	Odometer:	124,627 Kms	Good No:	19473319	Oil level	~		
VIN:	7AT0DH0KX10054243		12 1/02/ 14110	Service Histor		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			1
						Performance	~		
Key:	S	-0	S S		ls	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			
D=dent SPTSC OD SDPTC						Operation	~		<u> </u>
R = rust				TIO	7HH	Noise	v v		
PT = paint def C = crack	ect M			+	PT	Clutch			~
P = pin dent	Ho				JUII —	CV joints	~		
* = decals	sc gig			AL	ELAC	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes			
W = significant scuffs S W PT S W S SC									T
		Natarcan	ne defects & blemishe			Performance	~		──
Body Insp	pection Comments	Note: som	le délects & blemisne	is may not be disp	hayed in the diagram	Hand Brake		<u> </u>	Ļ
RR indicator not going. Vehicle has been repainted poorly. Paint coming off LF door. Rear bumper is						Tyres (lowest observed tread depth of tyres)			
damaged. Crack in paint below rear wiper. Tailgate release button damaged. Loose stereo wires in car. Central locking not working on RR door. Paint coming off roof trim. Aerial damaged						Left front		4	mm
Heater fan noisy.						Right front		4 mm	
[						Left rear		2	mm
Conditions During Body Inspection: Dry									mm
Under Comione Allader Deservation Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	r		
Front cross	member has surface rus	st.				Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators		~	
Panels	Poor					Dashboard warning lights	~		
Dackher-	Poor					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_					Window winder FR	~		
General Comments					Window winder RL	~			
Harsh gear change from 1 to 2 when cold. Parking guide in LF of front bumper is damaged.						Window winder RR	~		
Wear on RF						Rear view mirrors	~		
Drives ok.						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking		~	
,						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							1		
Inspected by: Roger King Date: 01 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....