

Basic Vehicle Condition Guide

Report ID: 19,474,617


Version: 1

Created: 01 May 2019

Make: Model: Hyundai Elantra **Body Style:** Hatchback Year: 2006 Registration: DFY921 Reg Expiry: 01 Jul 2019 WoF Expiry: **Odometer:** 09 Apr 2020 84,056 Kms **Good No:** 19474617 VIN: KMHDN51DR6U19034 **Next Service:** 92000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Boot stays worn Radio aerial faulty Only one remote working Engine oil leak

Interior Comment	<u>5</u>
Seats	Drivers seat worn, marks on seats
Carpets	Average
Panels	Drivers door panel cuts
Dachboard	Average

General Comments

Dashboard

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Inspected by: John Lindsay Date: 01 May 2019

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<i>V V</i>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	l depth	of tyre	 es)
Left front		1	mm
Right front	2		mm
Left rear	3		mm
Right rear	4		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			ı
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	v		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	•		
Window winder RR	<i>v</i>		
Rear view mirrors		./	
		-	
Radio (basic test only)			
CD (basic test only)	2		
Number of keys	2		
Central locking	-		
Remote locking	~		
C . N. (I			
Sat. Nav. (basic test only) Reversing camera			~

I have read and understood this condition guide.

Name:

Kms:

Signature: