

Signature:

Make:	Holden	Model:	Commodore	Body Style:	Sedan			Pass	Fail	N/A	
Year:	2010	-	FJA697	Reg Expiry:	28 Jan 2020		Engine				
	20 May 2020	Odometer:	163,865 Kms	Good No:	19475489	Oil level		~			
VIN:	6G1EX5EV1AL446138	Next Service:	171,000kms	Service Histor	y: Yes	Smoke & f	fumes	~			
Noto: This rea	oort is not a warranty					Performar	nce	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System					
arun meenan		purchase and ti	ins can be analiged i		indige.	Coolant co	ondition	<			
	SC S		SC D SC	S		Performar	nce	~			
Key:		=(0)		505		Radiator /	Hoses (visual)	~			
S = scratch D = dent						Transmissi	Transmission				
R = rust	sc w			210	Ell s	Operation	ı	~			
PT = paint defe	ect NP				111/1	Noise		~			
C = crack						Clutch				~	
P = pin dent	HIP				74116	CV joints				~	
* = decals	sc 916			70	ED PT	Wheel bea	arings	~			
SC = stone chips						Brakes					
W = significant scuffs SC S SD SD SD SD SD						Performance 🖌					
Podulaca	action Commonts	Note: son	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brak	(e	~			
body inspection comments						Tyres (lowe	Tyres (lowest observed tread depth of tyres)				
Reverse camera fail						Left front					
						Right fron	Right front		.0	mm	
						Left rear		5.		mm	
Conditions During Rody Inspections Dry							Right rear		-	mm	
Conditions During Body Inspection: Dry						Spare					
Under Carriage & Under Bonnet Inspection Comments						Suspension					
Rear wheel	-	•				· ·	on performance	~			
							performance	• •			
						Shock abs		~			
							•				
						Air Conditioning / Heater					
Interior Comments						Operation 🖌					
Seats Average											
Seals						Tail lights		 			
Carpets	Average							•			
	Poor					Indicators		v			
Panels							d warning lights	~		-	
Dashboa	rd Good	Good					ont & rear)	~			
						Window v		v			
General	Comments					Window v		•			
	<u>.omments</u>					Window v		~			
						Window v		~			
						Rear view		~			
						-	sic test only)	~			
						CD (basic		~			
						Number o	-	1			
Road Conditions During Test Drive: Dry						Central lo	-	~			
Engine Tim	ning Machanism	Time !	Chain			Remote lo	ocking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing	camera		~		
lun au +	thu Cathack							0			
Inspected	d by: Ca Thach					L	Date: 21 May 201				

I have read and understood this condition guide.

Name: