

Report ID: 19,475,721 Version: 4 Created: 06 Aug 2019

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	LAY999	Reg Expiry:	01 Nov 2019	Engine	1		L
WoF Expiry:	22 May 2020	Odometer:	310,372 Kms	Good No:	19475721	Oil level	~		
VIN:	JTEBU25J905011023	Next Service:	315,600	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			Р			Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust S A A S S S S S S S S S S S S S S S S						Operation 🖌			
PT = paint def	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dl				2416	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S		S S			Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
1 key remote working						Tyres (lowest observed tread depth of tyres)			
RR door ashtray missing						Left front	3 mm		mm
						Right front	2	2	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater	1		
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	//veluge					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Avelage					Dashboard warning lights	~		
Dashboa	rd Cracks					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
General Comments						Window winder FR	~		<u> </u>
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			
Dead Canditiana Duvin a Tast Driver a						Number of keys	1		
Road Conditions During Test Drive: Dry Central lock							~		<u> </u>
Engine Timing Mechanism: Timing Chain Remote locking							~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			v
Evidence of Cam Beit Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: Mathew Varghese Date: 06 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: