

Report ID: 19,476,269 Version: 2 07 May 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	FFA194	Reg Expiry:	28 Sep 2019	Engine			
WoF Expiry:	14 Jan 2020	Odometer:	143,144 Kms	Good No:	19476269	Oil level	~		
VIN:	JM0GH105100137575	Next Service:	153000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	S W				S D	Performance	~		
Key:	s	-0	SD S	$- \square$	30	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S P SC W			715	SDW	Operation	~		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	SRSC 91			The second	ALD S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D W S D S D W S D						Performance	~		
Podylogr	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	s)
Right front tyre inner edge wear						Left front 6 mm			mm
						Right front		3	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry					Right rear	5 mm		mm	
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
Steering performance						Steering performance	~		
Sh						Shock absorbers	~		
						Air Conditioning / Heater			
_						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	all seats we	orn				Head lights	~		
	driver mat	worp				Tail lights	~		
Carpets	unvermat	wom				Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanicmy Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: John Lindsay Date: 07 May 2019									

I have read and understood this condition guide.

Name:

Signature: