

Report ID: 19,476,488 Version: 2 16 May 2019 Created:

Signature:

| Make: | KIA | Model: | Cerato | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|------------------------|-----------------|------------------------|---------------------------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2013 | Registration: | JGK864 | Reg Expiry: | 29 Apr 2019 | Engine | | | |
| WoF Expiry: | 29 May 2020 | Odometer: | 78,090 Kms | Good No: | 19476488 | Oil level | ~ | | |
| VIN: | KNAFU512MD573244 | Next Service: | 80,000 | Service Histor | Y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Danta hava nat | hoon disponsion of | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | s sc | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | - HE | | | TIS | | Operation | ~ | | |
| R = rust PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74 <u>11</u> | CV joints | ~ | | - |
| * = decals | sc 916 | | | - Jul | | Wheel bearings | ~ | | |
| SC = stone chi | 7 | 26 | ليكالكي | 10- | * | Brakes | | | · |
| W = significan | t scuffs S | | | | | Performance | ~ | | |
| Bodylac | Dection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread | d depth | of tyre | s) |
| | | | | | | Left front | 5 | - | mm |
| | | | | | | Right front | 5 | | mm |
| | | | | | | Left rear | 6 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Front whee | l drive | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 11 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry Central Ion | | | | | | | ~ | | |
| | - | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Ca Thach Date: 16 May 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name: