

Basic Vehicle Condition Guide

Report ID: 19,478,456

Pass

V

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Created: 03 Jun 2019


Fail

N/A

Make: Model: Holden Cruze **Body Style:** Wagon Year: 2015 Registration: JHM91 Reg Expiry: 21 Sep 2019 WoF Expiry: **Odometer: Good No:** 01 Jun 2020 118,280 Kms 19478456 VIN: KL3JA35MJFK051459 Next Service: 133,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2WD

Interior Comments		
Seats	Average	
Carpets	wear and tear	
Panels	Average	
Dashboard	Good	

_	_
Conoral	Comments
General	COMMENTS

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Ca Thach

Evidence of Cam Belt Replacement: No

Kms:

	1	
-		
~		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	s)
	4	mm
	4	mm
	2	mm
	2	mm
	Yes	
~		
~		
~		
~		
~		
~		
~		
~		
~		
<i>'</i>		
~		
<i>'</i>		
	L	
~		
		-/
		<i>y</i>

I have read and understood this condition guide.

Name:

Signature:

03 Jun 2019

Date: