

Report ID: 19,478,619 Version: 3 11 Jun 2019 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	FUS573	Reg Expiry:	10 Oct 2019	Engine	1		
WoF Expiry:	21 Jun 2020	Odometer:	92,720 Kms	Good No:	19478619	Oil level	~		
VIN:	MM0DE10Y10014470	Next Service:	85,000	Service Histor	<b>/:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	W		S P SC			Performance	~		
Key:		-0	S PSC			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SD D			215	HIV	Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID			$\langle \rangle$	2016	CV joints	~		
* = decals	- Alt			Ta		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	t scuffs W		S S		S	Performance	~		
Body Incr	pection Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.0	mm
						Right front	6	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Wet						Right rear	5	5.0 n	
						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comet	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	_		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Bobby Zhong									
Inspected by: Bobby Zhong Date: 07 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....