


<b>Make:</b>	Mitsubishi	<b>Model:</b>	L300	<b>Body Style:</b>	Van
<b>Year:</b>	2005	<b>Registration:</b>	HSW675	<b>Reg Expiry:</b>	30 Sep 2019
<b>WoF Expiry:</b>	26 Jul 2020	<b>Odometer:</b>	221,480 Kms	<b>Good No:</b>	19478626
<b>VIN:</b>	JMASNP05V4A800455	<b>Next Service:</b>	224000	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

RR taillight damaged  
RR window cannot be locked

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**

Rear wheel drive

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Poor
Dashboard	Average

**General Comments**

Black Smoke from exhaust on cold start  
Central locking fail

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 198,085

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes		✓	
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	5	mm	
Left rear	5	mm	
Right rear	5	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking		✓	
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Ca Thach

Date: 16 Aug 2019

I have read and understood this condition guide.

Name: .....

Signature: .....