

Basic Vehicle Condition Guide

Report ID: 19,478,912


Version: 1

Created: 28 May 2019

Make: Model: Holden Cruze **Body Style:** Wagon Year: 2016 Registration: JZN974 Reg Expiry: 28 Jul 2019 WoF Expiry: **Odometer: Good No:** 29 Jul 2019 83,360 Kms 19478912 VIN: KL3JA35MJGK336580 **Next Service:** 90,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right sill damage, left sill dented

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive Rear brake pads low Engine oil leak - rear main seal

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A		
Engine					
Oil level	>				
Smoke & fumes	~				
Performance	V				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	>				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	>				
Tyres (lowest observed tread	depth	of tyre	es)		
Left front	6		mm		
Right front	6		mm		
Left rear	3		mm		
Right rear	4		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Poversing camera	ı	1			

Reversing camera

Signature:

28 May 2019 Inspected by: Ca Thach

Name: