

Report ID: 19,479,421 Version: 3 20 May 2019 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:	JQD979	Reg Expiry:	04 Aug 2019	Engine			
WoF Expiry:	31 Jan 2020	Odometer:	94,575 Kms	Good No:	19479421	Oil level	~		1
VIN:	7AT0H63YX16088892	Next Service:		Service Histor		Smoke & fumes	~		+
						Performance	~		+
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			1
						Performance	~		
Key:		-0	S S			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation 🖌			1
R = rust				10	JHIH	Noise	~		
PT = paint defect C = crack						Clutch	V		~
P = pin dent	Ho				JUII ——	CV joints	~		
* = decals SSC PIP						Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs						Performance			T
		Notor con					~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	<ul> <li></li> <li><td></td><td></td></li></ul>		
LH wing mirror not working Dashboard panel misaligned						Tyres (lowest observed tread depth of tyres)			
Dashboard panel misaligned						Left front			mm
						Right front		3	mm
						Left rear	7 mm		
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Front wheel drive						Suspension			
Front whee	l drive					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	<del></del>
Interior Comments						Operation 🖌			
Good						Electrical / Accessories		1	
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
		·				Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 20 May 2019									
Inspected by. Ca mach Date: 20 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....