

Report ID: 19,479,961 Version: 1 06 May 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	,					Engine	rass	Fall	N/A
WoF Expiry:	2017	Registration:	KYG38	Reg Expiry:	28 Sep 2019				
	29 Sep 2020	Odometer:	61,723 Kms	Good No: Service Histor	19479961	Oil level	~		
VIN:	MR0GA3DD10026181	Next Service:		Service Histor	V: No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
This report is	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
	· ·	•	5		5	Coolant condition	~		
Key:	S	\sim	S S D		S	Performance	~		
S = scratch		\sim (O)		≠5(O)~	$\overline{}$	Radiator / Hoses (visual)	~		
						Transmission			
R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
e decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan	S		S D S D		S	Performance	~		
Body Inst	paction Comments	Note: som	ne defects & blemi	shes may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Rear bumper alignment						Tyres (lowest observed tread depth of tyres)			
Right headlight moisture						Left front	3 mm		
						Right front	4		mm
						Left rear	2		mm
Conditions During Body Inspection: Dry						Right rear	3		mm
Conditions During Body Inspection: Dry						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Operation 🖌			
		burn hole, mark	s front seats						
Seats						Head lights Tail lights	~		
Carpets	Average						~		
	Average					Indicators	~		
Panels	/ verage					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Comment						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	<		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Kyle Mills-Brown Date: 06 May 2019									

I have read and understood this condition guide.

Name:

Signature: