

Report ID: 19,480,112 Version: 2 31 May 2019 Created:

Make:	Toyota	Model:	Allex	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2001	Registration:	CGN189	<b>Reg Expiry:</b>	04 Apr 2020	Engine	1		
WoF Expiry:	23 May 2020	Odometer:	182,637 Kms	Good No:	19480112	Oil level	~		
VIN:	7A8H63Y0704081642	Next Service:	190163	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	V		
Key:	SC	-0		$- \square$		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	w dla			715	HILW	Operation	~		
PT = paint def				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	110				74114	CV joints	~		
* = decals	DSC 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S S W						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	oftvre	25)
						Left front 6.0 mm			
						Right front		.0	 mm
						Left rear			mm
Conditions Duving Rody Inspection. West						Right rear			 mm
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Operation 🖌			
Good									
Seats							~		
Carpets	Good					Tail lights Indicators	<b>v</b>		
	Good						~		
Panels						Dashboard warning lights Wipers (front & rear)	V 		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	<b>v</b>		
						Window winder FL Window winder FR	V 		
General (	<u>Comments</u>					Window winder FR	<b>v</b>		
						Window Winder RL Window winder RR	~		
							~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	2		~
						Number of keys	3		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera			~
Inspected by: Brian Hill Date: 07 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....