

Basic Vehicle Condition Guide

Report ID: 19,480,901


Version: 3

Created: 30 May 2019

Make: Model: Holden Barina Spark **Body Style:** Hatchback Year: 2010 Registration: FPL572 Reg Expiry: 10 Aug 2019 WoF Expiry: **Odometer: Good No:** 19480901 27 May 2020 75,431 Kms VIN: KL3MF48D9BC532887 Next Service: 85500 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | | - , | | | |
|------------------------------|-----------------|---------|-----|--|--|
| | Pass | Fail | N/A | | |
| Engine | | 1 | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | \(\triangle \) | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | \(\times \) | | | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 4 | .0 | mm | | |
| Right front | 3.0 | | mm | | |
| Left rear | 2.0 | | mm | | |
| Right rear | 3.0 | | mm | | |
| Spare | Yes | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | | | | | |
| Dashboard warning lights | \(\times \) | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | I | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | i | | | |

I have read and understood this condition guide.

Stuart Melbourne

Name:

Signature:

07 May 2019

Date: