



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,481,481
Version:	4
Created:	09 Sep 2019

Make:	Nissan	Body Style:	Sedan
Model:	Fuga	VIN:	7AT0DH8GX19221238
Year:	2006	Odometer:	94,694 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good						
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	7.0	mm	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>7.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	7.0	mm	63	Left Rear	7.0	mm	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	7.0	mm	65	Spare	Yes	86	L/H Mirror	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good						
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	88	R/F Guard	Good				
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	89	L/H Doors	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	90	R/H Doors	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Average</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	74	Seats	Good	75	Carpets	Average	92	R/H Sill	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>76</td><td>Panels</td><td>Average</td><td>77</td><td>Dashboard</td><td>Average</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	46	Handbrake	✓ <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	76	Panels	Average	77	Dashboard	Average	93	Boot/Tail Gate	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>78</td> <td>Fuel Cap</td> <th>✓</th> <td>94</td> <td>Front Bumper</td> <td>Good</td>	78	Fuel Cap	✓	94	Front Bumper	Good				
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	49	Number of Keys	2	95	Rear Bumper	Good						
18	Odometer	✓	Engine		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>	51	Smokes and Fumes	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good				
19	Rev Counter	✓	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td></th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td></th>	54	Starter Motor	✓ <td>97</td> <td>Bonnet</td> <td>Good</td>	97	Bonnet	Good			
20	Fuel Gauge	✓	55	WOF	✓	56	WOF	✓ <td>57</td> <td>WOF</td> <th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th>	57	WOF	✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>	98	Fuel Cap	✓			
21	Wipers Front/Rear	✓	58	WOF	✓ <td>59</td> <td>WOF</td> <th>✓<td>60</td><td>WOF</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	59	WOF	✓ <td>60</td> <td>WOF</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	60	WOF	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓			
22	Window Opener FL	✓	61	WOF	✓ <td>62</td> <td>WOF</td> <th>✓<td>63</td><td>WOF</td><th>✓<td>100</td><td>WOF</td><th>✓</th></th></th>	62	WOF	✓ <td>63</td> <td>WOF</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	63	WOF	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓			
23	Window Opener FR	✓	64	WOF	✓ <td>65</td> <td>WOF</td> <th>✓<td>66</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	65	WOF	✓ <td>66</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	66	WOF	✓ <td></td> <td></td> <td></td>						
24	Window Opener RL	✓	67	WOF	✓ <td>68</td> <td>WOF</td> <th>✓<td>69</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	68	WOF	✓ <td>69</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	69	WOF	✓ <td></td> <td></td> <td></td>						
25	Window Opener RR	✓	70	WOF	✓ <td>71</td> <td>WOF</td> <th>✓<td>72</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	71	WOF	✓ <td>72</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	72	WOF	✓ <td></td> <td></td> <td></td>						
26	Rear View Mirrors	✓	73	WOF	✓ <td>74</td> <td>WOF</td> <th>✓<td>75</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	74	WOF	✓ <td>75</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	75	WOF	✓ <td></td> <td></td> <td></td>						
27	Radio (Basic Test Only)	✓	76	WOF	✓ <td>77</td> <td>WOF</td> <th>✓<td>78</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	77	WOF	✓ <td>78</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	78	WOF	✓ <td></td> <td></td> <td></td>						
28	CD (Basic Test Only)	✓	79	WOF	✓ <td>80</td> <td>WOF</td> <th>✓<td>79</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	80	WOF	✓ <td>79</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	79	WOF	✓ <td></td> <td></td> <td></td>						
29	Boot Open Switch	✓	81	WOF	✓ <td>82</td> <td>WOF</td> <th>✓<td>83</td><td>WOF</td><th>✓<td></td><td></td><td></td></th></th>	82	WOF	✓ <td>83</td> <td>WOF</td> <th>✓<td></td><td></td><td></td></th>	83	WOF	✓ <td></td> <td></td> <td></td>						

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	09 Sep 2019
---------------	---------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--