



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,482,136
Version:	2
Created:	09 Sep 2019

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	VIN:	7AT0GF1RX19002383
Year:	2010	Odometer:	112,194 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good				
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	6.0	mm	86	L/H Mirror	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>6.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	6.0	mm	87	L/F Guard	Good					
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	7.0	mm	88	R/F Guard	Good					
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	7.0	mm	89	L/H Doors	Good					
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Cambelt	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	68	Heater Fan	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	No	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Average</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	74	Seats	Average	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓</th> <td>75</td> <td>Carpets</td> <td>Average</td> <td>76</td> <td>Panels</td> <td>Average</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	46	Handbrake	✓	75	Carpets	Average	76	Panels	Average	95	Rear Bumper	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>77</td> <td>Dashboard</td> <td>Average</td> <td>78</td> <td>WOF</td> <th>✓</th> <td>96</td> <td>Roof</td> <td>Good</td>	77	Dashboard	Average	78	WOF	✓	96	Roof	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>79</td> <td>Fuel Cap</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	49	Number of Keys	2	79	Fuel Cap	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓
18	Odometer	✓	Engine		50	Oil Level	✓ <td>80</td> <td>Mud Flaps</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	80	Mud Flaps	✓ <td>99</td> <td>Mud Flaps</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	99	Mud Flaps	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>100</td><td>WOF</td><th>✓<td>100</td><td>WOF</td><th>✓</th></th></th>	52	Performance	✓ <td>100</td> <td>WOF</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	100	WOF	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓			
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	54	Starter Motor	✓									
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	09 Sep 2019
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--