

Report ID: 19,482,382 Version: 3 05 Jun 2019 Created:

| Make: | Skoda | Model: | Octavia | Body Style: | Sedan | | Pass | Fail | N/A | |
|--|--|------------------|------------------------|-------------------|----------------------|------------------------------|--------|------------|------------|--|
| Year: | 2015 | Registration: | JCG576 | Reg Expiry: | 25 Aug 2019 | Engine | | | | |
| WoF Expiry: | | Odometer: | 136,658 Kms | Good No: | 19482382 | Oil level | ~ | | | |
| VIN: | TMBBE9NE7F0199317 | | | Service Histor | | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | | | | | Noise | ~ | | | |
| | a guide only. Conside sting undertaken. The | | | | | Cooling System | V | | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | | |
| | | | | | | Performance | ~ | | | |
| Key: | w so | 0 | | | | Radiator / Hoses (visual) | ~ | | <u> </u> | |
| S = scratch | Se | A CO | | 10c | X | Transmission | V | | | |
| D = dent | s sc | | | The | BID PT W | Operation | ~ | | <u> </u> | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | | |
| PT = paint defe C = crack | ect | | | + | | Clutch | ~ | | | |
| C = Crack P = pin dent | Ho | | | | JIII — | | | | ~ | |
| * = decals | sc pp | | | SI_ | | CV joints | ~ | | <u> </u> | |
| SC = stone chi | ps US | VA | | 10 | | Wheel bearings Brakes | ~ | | | |
| W = significan | t scuffs PT SC W | _0 | IS I | | | | | | | |
| | | | | | | Performance | ~ | | <u> </u> | |
| <u>Body Insp</u> | pection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | <i>c</i> . | Ļ | |
| | | | | | | Tyres (lowest observed tread | | | | |
| | | | | | | Left front | 4 | | mm | |
| | | | | | | Right front | | 1 | mm | |
| | | | | | | Left rear | | 5.5 mr | | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.5 mm | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | | |
| | - | metinspectic | <u>n comments</u> | | | Suspension | | | . <u> </u> | |
| Front whee | l drive | | | | | Suspension performance | ~ | | <u> </u> | |
| | | | | | | Steering performance | ~ | | <u> </u> | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | 1 | | . <u> </u> | |
| Interior Comments | | | | | | Operation 🖌 | | | | |
| Interior Comments Good Good | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| Carpets | Driver floo | or mats wear and | tear | | | Tail lights | ~ | | | |
| carpets | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| Dachhar | Good | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| <u>General C</u> | <u>Comments</u> | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 1 | | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | | |
| . | - | | · | | | Remote locking | ~ | | | |
| - | ming Mechanism: | Timing (| | | | Sat. Nav. (basic test only) | ~ | | | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ | |
| Inspected | d by: Ca Thach | | | | | Date: 05 Jun 20 | 19 | | | |

I have read and understood this condition guide.

Name:

Signature: