

Report ID: 19,482,428 Version: 1 09 May 2019 Created:

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	FZP90	Reg Expiry:	05 Jul 2019	Engine	1		I
WoF Expiry:	03 Aug 2019	Odometer:	113,201 Kms	Good No:	19482428	Oil level	~		
VIN:	JSAGYB51S00300673	Next Service:	123000z	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S S	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc di			715	HILS	Operation	~		
PT = paint def				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HE				7414	CV joints	~		
* = decals	s sc gle			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S D S D						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
								mm	
						Right front	3	3	mm
						Left rear	e		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tyre need r	eplacement					Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / H							1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
2wd						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	· ·		
			-			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Bobby Zhong Date: 09 May 2019									

I have read and understood this condition guide.

Name:

Signature: