

Basic Vehicle Condition Guide

Report ID: 19,482,686


Version: 2

Created: 23 May 2019

Make: Model: Subaru Outback **Body Style:** SUV Year: 2015 Registration: JDA624 Reg Expiry: 17 Aug 2019 WoF Expiry: **Odometer: Good No:** 20 May 2020 110,182 Kms 19482686 VIN: JF2BS9KC2FG006451 Next Service: 118,850kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

AWD

Engine oil leak Transmission oil leak

Interior Comments	<u>5</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Xinghui Lin Date: 23 May 2019

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
•		•
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
-	7	mm
-	7	mm
3		mm
4		mm
Yes		
	Yes	
	Yes	
·	Yes	
<i>V</i>	Yes	
<i>V V</i>	Yes	
<i>V V V</i>	Yes	
V V V	Yes	
V V	Yes	
V V V V	Yes	
<i>v</i>	Yes	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes	
V V V V V	Yes	
V V V V V	Yes	
V V V V V V V	Yes	
V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V	Yes	
V V V V V V V V V V V V V V V V V V V	Yes	
V V V V V V V V V V V	Yes	
	V V V V V depth	v v v v v v depth of tyre

Signature: