

Report ID: 19,483,302 Version: 1 12 May 2019 Created:

Make:	Ford	Model:	Courier	Body Style:	Utility		Pass	Fail	N/A
Year:	1994	Registration:	SX5647	Reg Expiry:	30 Oct 2019	Engine	1 435	i uli	
WoF Expiry:		Odometer:	129,609 Kms	Good No:	19483302	Oil level	~		T
VIN:	7A5AAASACPRP66076			Service Histor		Smoke & fumes			<u> </u>
viiv.	7A3AAA3ACPRP0007(NEXT SELVICE.	130,000	Service mistor	y. NO		~		
Note: This report is not a warranty						Performance		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
						Coolant condition	~		<u> </u>
Key:	S		D			Performance	~		<u> </u>
S = scratch	2	(0)		(O)	\checkmark	Radiator / Hoses (visual)	~		
D = dent				100	ADD	Transmission			
R = rust	R 9B					Operation	~		
PT = paint def	ect NM					Noise	~		
C = crack						Clutch	~		
P = pin dent	sc dl				2414	CV joints			~
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		1
body inspection comments						Tyres (lowest observed tread	d depth	oftyre	<u>)</u> 25)
						Left front 7			mm
						Right front	7		mm
						Left rear		3	mm
Conditions During Rody Inspection: Wat						Right rear		2	mm
Conditions During Body Inspection: Wet						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2WD		•				Suspension performance	~		1
Underbody	surface rust					Steering performance	~		
Minor oil le	ak Engine and gearbox						-		
						Shock absorbers	~		
		Air Conditioning / Heater							
Interior Comments						Operation			~
Average						Electrical / Accessories			1
Seats	, weitige					Head lights	~		
Carpets	Average					Tail lights	~		
	NA!!	***				Indicators	~		
Panels	Missing pa	15		Dashboard warning lights	~				
Dashboa	rd Missing pa	rts				Wipers (front & rear)	~		
Dashboa	iu - ·					Window winder FL		~	
_						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Engine misfiring Missing parts - FL and rear seat, FL door pad, AC knobs, Console panel, Glove box lid, Audio unit. FL door						Window winder RR			~
window winder handle						Rear view mirrors	~		
Drive belt n	oisy					Radio (basic test only)			~
						CD (basic test only)			~
						Number of keys	2		1
Road Conditions During Test Drive: Wet						Central locking			~
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			v
Evidence	of Cam Belt Replace	ement: N	10	Kms:		Reversing camera			~
		•							_ _
Inspecte	d by: Mathew Varghe	Date: 12 May 20)19						
I have read	and understood thi	is condition o	guide. Name: .			Signature:			