

I have read and understood this condition guide.

Report ID: 19,483,855 Version: 1 13 Jun 2019 Created:

Signature: .....

| Make:  | Renault   | Model:               | Megane CC              | Body Style:        | Sports Car           |                              | Pass    | Fail    | N/A |
|--|---|----------------------|------------------------|--------------------|----------------------|------------------------------|---------|---------|-----|
| Year:  | 2005  | <b>Registration:</b> | DBR394                 | <b>Reg Expiry:</b> | 01 Oct 2019          | Engine                       | •       |         |     |
| WoF Expiry:  | 06 Sep 2018                                     | Odometer:            | 121,021 Kms            | Good No:           | 19483855             | Oil level                    | ~       |         |     |
| VIN:   | VF1EM050A34632980                               | Next Service:        | 91700                  | Service Histor     | <b>y:</b> No         | Smoke & fumes                | ~       |         |     |
| No. The  |   |                      |                        |                    |                      | Performance                  | ~       |         |     |
|  | port is not a warranty<br>a quide only. Conside | eration is made      | for age and mileage    | . Parts have not   | been dismantled or   | Noise                        | ~       |         |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |   |                      |                        |                    |                      | Cooling System               |         |         |     |
| a full mechan  | ical inspection prior to                        | purchase and t       | his can be arranged fo | or an additional o | narge.               | Coolant condition            | ~       |         |     |
|  | SC  |                      | S                      |                    |                      | Performance                  | ~       |         |     |
| Key:   |   | -0                   |                        | 500-               |                      | Radiator / Hoses (visual)    | ~       |         |     |
| S = scratch<br>D = dent  |   |                      |                        |                    |                      | Transmission                 |         |         |     |
| B = rust   | s sc  |                      |                        | 710                | HIVS                 | Operation                    | ~       |         |     |
| PT = paint defe  | ect NP  |                      |                        |                    | 70111                | Noise                        | ~       |         |     |
| C = crack  |   |                      |                        |                    |                      | Clutch                       |         |         | ~   |
| P = pin dent   | HID   |                      |                        | $\langle \rangle$  | 74116                | CV joints                    | ~       |         |     |
| * = decals   | - Alt   | 10                   |                        | 10                 |                      | Wheel bearings               | ~       |         |     |
| SC = stone chips<br>W = significant scuffs   |   |                      |                        |                    |                      | Brakes                       |         |         |     |
|  |   |                      |                        |                    |                      | Performance                  | ~       |         |     |
| Body Incr  | pection Comments                                | Note: son            | ne defects & blemishes | s may not be disp  | layed in the diagram | Hand Brake                   | ~       |         |     |
|  |   |                      |                        |                    |                      | Tyres (lowest observed tread | d depth | of tyre | es) |
|  |   |                      |                        |                    |                      | Left front 4                 |         |         | mm  |
|  |   |                      |                        |                    |                      | Right front                  |         | 3       | mm  |
|  |   |                      |                        |                    |                      | Left rear                    | 4       |         | mm  |
| Conditions During Body Inspection: Dry   |   |                      |                        |                    |                      | Right rear                   |         | 3       | mm  |
|  |   |                      |                        |                    |                      | Spare                        |         |         |     |
| Under Carriage & Under Bonnet Inspection Comments  |   |                      |                        |                    |                      | Suspension                   |         |         |     |
|  |   |                      |                        |                    |                      | Suspension performance       | ~       |         |     |
|  |   |                      |                        |                    |                      | Steering performance         | ~       |         |     |
|  |   |                      |                        |                    |                      | Shock absorbers              | ~       |         |     |
|  |   |                      |                        |                    |                      | Air Conditioning / Heater    | 1       | L       |     |
|  |   |                      |                        |                    |                      | Operation                    | ~       |         |     |
| Interior Comments  |   |                      |                        |                    |                      | Electrical / Accessories     |         |         |     |
| Seats  | Average   |                      |                        |                    |                      | Head lights                  | ~       |         |     |
|  | Average   |                      |                        |                    |                      | Tail lights                  | ~       |         |     |
| Carpets  | / Weitage                                       |                      |                        |                    |                      | Indicators                   | ~       |         |     |
| Panels   | Average   |                      |                        |                    |                      | Dashboard warning lights     | ~       |         |     |
|  | Average   |                      |                        |                    |                      | Wipers (front & rear)        | ~       |         |     |
| Dashboa  | rd  |                      |                        |                    |                      | Window winder FL             | ~       |         |     |
|  | 1   |                      |                        |                    |                      | Window winder FR             | ~       |         |     |
| General Comments   |   |                      |                        |                    |                      | Window winder RL             |         |         | ~   |
|  |   |                      |                        |                    |                      | Window winder RR             |         |         | ~   |
|  |   |                      |                        |                    |                      | Rear view mirrors            | ~       | -       |     |
|  |   |                      |                        |                    |                      | Radio (basic test only)      | ~       |         |     |
|  |   |                      |                        |                    |                      | CD (basic test only)         | ~       |         |     |
|  |   |                      |                        |                    |                      | Number of keys               | 2       |         |     |
| Road Conditions During Test Drive: Dry   |   |                      |                        |                    |                      | Central locking              | ~       |         |     |
|  |   |                      |                        |                    |                      | Remote locking               | ~       |         |     |
| Engine Timing Mechanism: Unknown   |   |                      |                        |                    |                      | Sat. Nav. (basic test only)  |         |         | ~   |
| Evidence   | of Cam Belt Replac                              | ement: N             | lot Applicable         | Kms:               |                      | Reversing camera             |         |         | ~   |
|  |   |                      |                        |                    |                      | _                            | 1       |         |     |
| Inspected by: Donovan Matara Date: 13 Jun 2019   |   |                      |                        |                    |                      |                              |         |         |     |
|  |   |                      |                        |                    |                      |                              |         |         |     |

Name: .....