

Basic Vehicle Condition Guide

Report ID: 19,484,231


Version: 1

Created: 09 May 2019

Make: Model: Honda Accord **Body Style:** Sedan Year: 2005 Registration: CLZ69 Reg Expiry: 19 Jul 2019 WoF Expiry: **Odometer:** 20 Sep 2019 286,501 Kms **Good No:** 19484231 VIN: JHMCL95305C203598 Next Service: 275500 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper loose Rear bumper trim loose Left rear 1/4 window smashed Front spoiler alignment right and left side Bonnet trim broken

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Pedals worn

| Interior Comments | | | |
|-------------------|---------------------------------|--|--|
| Seats | seats stained, driver seat worn | | |
| Carpets | driver carpet worn | | |
| Panels | right rear scratches | | |
| Dashboard | Average | | |

General Comments

Inspected by:

Right outer cv joint leaking grease Power steering leaking oil Clutch pedal heavy to press and squeaking

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement:

Not Applicable Kms:

| | Pass | Fail | N/A | |
|--|--|------|----------|--|
| Engine | | - | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | \(\triangle \) | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | V | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | ~ | | | |
| CV joints | | ~ | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 5 | mm | |
| Right front | : | 2 | mm | |
| Left rear | | 1 | mm | |
| Right rear | 2 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | | ~ | | |
| Shock absorbers 🗸 | | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\times \) | | | |
| Dashboard warning lights | | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \(\times \) \(\t | | - | |
| Window winder FR | ' | | | |
| Window winder RL | ' | | | |
| Window winder RR | | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | V | | - | |
| CD (basic test only) | 1 | | | |
| Number of keys | 1 | | | |
| Central locking | V | | | |
| Remote locking | | | | |
| Sat. Nav. (basic test only) | | | <i>V</i> | |
| Reversing camera | | | | |

I have read and understood this condition guide.

John Lindsay

Name:

Signature:

09 May 2019

Date: