

Report ID: 19,485,708 Version: 1 14 May 2019 Created:

Make:	Toyota	Model:	OPA	Body Style:	SUV		Pass	Fail	N/A
Year:	2000	Registration:	GHL719	Reg Expiry:	19 Oct 2019	Engine			
WoF Expiry:	11 Oct 2019	Odometer:	217,349 Kms	Good No:	19485708	Oil level	~		
VIN:	7AT0H63WX11004038	Next Service:	219000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
			S P SC S P SC			Performance	~		
Key:	S SC	-0	SPSC SPSC	-01-	S D C SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SDCSC			715	HILS	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					S SC	Clutch	-		~
P = pin dent					741L	CV joints	~		•
* = decals	S PT SC 916			- NL		Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S S S S S S S S S S S S S						Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	blaved in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	-	of tyre	() ()
There is a base for something still attached to the LF guard,									
						Right front			mm
						Left rear		3	mm
			_			Right rear		5	
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							-		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Average						Electrical / Accessories			
Seats	5					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	, weitige					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
- Engine Ti	ning Mechanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or cam belt keplac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 14 May 2019									

I have read and understood this condition guide.

Name:

Signature: